IN	TEL	LOF	ΑX	5

## Approved For Release 2002/07/15 : CIA-RDP80-00810Ap02809680002-7

		.,
	_	,
~		F
- (	. 1	
_	. 1	
	) '	$\overline{}$

CLASSIFIC COUNTRY Fast Germany	ATION S.CRUET. SECURITY DIFFORMATION REPORT	25X1A NO
TOPIC Schoenhauser Demm As	rfield	
EVALUATION 25X1X	PLACE_OBTAINED	
DATE OF CONTENT	NAMES OF THE PROPERTY OF THE P	25X1C
DATE OBTAINED	25X1CDATE PREPARED13_A	
REFERENCES		
PAGESENCLOSURES	(NO. & TYPE)	efficiency and the financial state of the second of the state of the state of the state of the second of the secon
REMARKS	*	er beraum in som er state besamt en som en state en set en en som en
	25X1X	

25X1A

Damm airfield. A wood path at the southeast and another at the northwest of the field were blocked by recently erected barriers. No runway mats were observed at the field. Source determined that such runway mats were shipped away from Wudicke.

25X1A

Comment. Schoenhauser Damm airfield, about 500 x 2,800 meters, was established in 1952. In June 1953, piled up runway mats were observed at the field. The present report indicates that these runway mats had been shipped away. It remains to be seen whether the transfer is connected with a report from Beutzen according to which a usually reliable source stated that the runway mattings at Beutzen-Litten airfield were unsuitable, as they cut to pieces the tires of landing planes. It is possible that there exist a type of runway mat which do not come up to the requirement and are therefore shipped from the airfields. It is believed that Schoenhauser Damm airfield is not serviceable at present.

CLASSIFICATION SECRE